



Spare parts kits for older valves, page 1

VALVE	YEAR	COMMENT	SPARE. PART	RSK NO:
501-15 och 22	-1987	Manifold. DISCONTINUED, Replaced by 506	LK 681	4311729
506-15 och 22	-1992	Manifold with drain. DISCONTINUED, Replaced by 508	LK 681	4311729
507-15	-1992	Manifold. DISCONTINUED, Replaced by 509	LK 681	4311729
508-15 och 22	1991-	Manifold without drain. Replaces 501 and 506	LK 684	4311733
509-15	1994-	Manifold. Replaces 507	LK 684	4311733
510 och 511	1994-	Safety valves for the heating side		
513	-1997	Safety valve. DISCONTINUED, Replaced by 514		
514	-1997	Safety/draining valve. Replaces 513 and 518		
518	-1997	Safety/draining valve, -1997. Permits drainage in combination with 508. DISCONTINUED, Replaced by 514	LK 686 (Draining valve)	4311740
522-15	-1986	Vacuum valve. DISCONTINUED, Replaced by 523		
523-15	1986-	Vacuum valve. Replaces 522		
535	1991-2005	5 Filling valve angled with conical shut-off. DISCONTINUED, Replaced by 535 with ball valve shut-off	LK 685	4311739
535	2005-	Filling valve angled with ball valve shut-off.		
536	1993-2005	Filling valve straight, with conical shut-off. DISCONTINUED, Replaced by 536 with ball valve shut-off	LK 685	4311739
536	2005-	Filling valve straight with ball valve shut-off. Replaces 536 with conical shut-off		
537	2005-	Filling valve straight with ball valve shut-off G $\frac{3}{4}$ " ext. thread.		
540-22	-1983	Valve combination, one-piece valve housing. DISCONTINUED, Replaced by 541	LK 680 / 681	4920721 / 4311729



Spare parts kits for older valves, page 2

VENTIL	ÅR	KOMMENTAR	REP. SATS	RSK NR:
541-22	-1992	Valve combination, with drain. DISCONTINUED, Replaced by 548	LK 683 / 681	4920723 / 4311729
548-22	1992-	Valve combination, without drain. Replaces 541	LK 683 / 684	4920723 / 4311733
560-15	2000-	Valve combination without drain.	LK 688 / 684	4920722 / 4311733
545-22	1983-	Mixing valve for 541 and 548. Similar to 550-22, but with tube adapter on the KV connection.	LK 683	4920723
550-15 och 22 old mods.	-1988	Mixing valve. DISCONTINUED	LK 680	4920721
550-15 och 22	1988-	Mixing valve. Replaces previous model. Includes 2 drive flange models, both included in spare parts kit	LK 683	4920723
580-G25/22	-1984	Water meter coupling, -1984. DISCONTINUED. Replaced by 581. Replace the entire connection to 582 + replacement sleeve, art. no. 0002323 (016019)		
581-G25/22	-1984	Water meter coupling. DISCONTINUED. Replaced by 582. Replace the entire connection to 583 + replacement sleeve, art. no. 0002323 (016019)		
582-G25/22	1985-	Water meter coupling. DISCONTINUED: Replaced by 583. Replace the entire connection to 583. Ball valve shut-off.		
583-G25/22	2000-	Water meter coupling, 2000-. Water meter coupling. Replaces 580, 581 and 582. Ball valve shut-off.		
905-15	1991-	Draining valve		
520-G25	2006	Filter & Filter holder		022094
520-G32	2006	Filter & Filter holder.		022096